Company Name
Company Contact

CONSTRUCTION OBSERVATIONS RESPONSE LOG

Revision
Updated

Contractor-side response tracker | Link each response to the issuer's observation reference

COMPACT / A4 LANDSCAPE | one issue per row | use related document for full evidence

Observation ID	Issued date	Location	Division	Finding / description	Resolved via	Submission ref	Submitted date	Status
OBS-031	2026-10-12	Tower A / R405	Finishes	Loose tile at room entrance	WIR	WIR-217	2026-10-17	Under review
OBS-032	2026-10-14	B2 / Pump room	MEP	Pipe support spacing questioned	Clarification	LTR-092	2026-10-15	Submitted
OBS-033	2026-10-19	Block B / Roof	Waterproofing	Roof drain termination issue	WIR	WIR-222	2026-10-23	Closed
OBS-034	2026-10-22	Tower A / MEP	Plumbing	Pressure test leak	WIR	WIR-225	2026-10-28	Reinspection due
OBS-035	2026-10-25	Tower B / Elev. 4	Façade	Proposed change to panel detail	VR / TQ	VR-012	2026-10-27	Under review

VR, objection or WIR are example response routes only; the project procedure and contract determine validity.
Use the original observation ID; Submitted does not mean Accepted or Closed. Enter the reference of the actual response.

Generated by quollnet